


mainair sports



MAINAIR SPORTS LIMITED Alma Industrial Estate
Rochdale, Lancashire, England. OL12 0HQ.
Tel.(0706) 55134 Telex 635091 ALBION G ATTEN.MAIN

Date: 4th November, 1981

Our Ref: JAH/EEW

Your Ref:

TRI-FLYER SERVICE BULLETIN 4

This information must be acted upon immediately

1) EXHAUSTS - see previous Service Bulletin

The Huntair exhaust is definitely the best for performance. However, we are having problems with this and since the last bulletin a tail pipe has broken off one of the latest types.

BEFORE FLYING YOUR TRI-FLYER AGAIN YOU MUST SECURE THE TAIL PIPE BY EITHER WELDING A STRAP TO IT OR SWAGE A WIRE RETAINER TO IT SO THAT IF IT DOES FAIL IT DOES NOT GO THROUGH THE PROP.

John Hudson.
Mainair Sports.