


mainair sports



Mainair Sports Ltd.
Unit 2, Alma Industrial Estate, Regent Street
Rochdale, Lancs. OL12 0HQ England.
Telephone: Rochdale (0706) 55134
Telex: 635091 Albion G-Attention/Mainair
Fax: 0706 31561

09/03/92

SERVICE BULLETIN NO.39 - SUBJECT H.T.COIL MOUNTING PLATE BOLTS

Ref.- All aircraft fitted with 503 2V TPI[Twin plug ignition] engine.

Before the next flight,check the bolts that fix the mounting plate onto the engine block,for tightness.

If it is found slack,remove and re-fit with LOCTITE retainer 638.

Carry out a visual check on the security of the coil mounting,as part of your pre-flight check.

JOHN BRIDGE

TECHNICAL MANAGER

