


mainair sports



Mainair Sports Ltd.
Unit 2, Alma Industrial Estate, Regent Street
Rochdale, Lancs. OL12 0HQ England.
Telephone: Rochdale (0706) 55134
Telex: 635091 Albion G-Attention/Mainair
Fax: 0706 31561

MAINAIR SERVICE BULLETIN NO.38A - MANDATORY

MARCH 3rd 1992

A problem has been identified on the GREY fuel primer bulbs fitted to Mainair aircraft.

The fault could restrict the fuel flow, and result in an engine failure

If your aircraft is fitted with a grey primer bulb, contact your dealer immediately, who will then carry out a modification involving the replacement of the grey bulb with a new type.

Aircraft must not be flown with a grey primer bulb fitted.

TAKE IMMEDIATE ACTION

Contact your dealer now .

If you have any difficulty , then contact Mainair Sports direct.

JOHN BRIDGE

TECHNICAL MANAGER

